

A MOVING AVERAGE CONTROL CHART FOR THE
SAMPLE MEAN BASED ON A ROBUST ESTIMATOR
OF SCALE

by

SUFFIAH BINTI JAMEL

Dissertation submitted in partial fulfillment
of the requirements for the degree
of Master of Science in Statistics

April 2009

830471

rb
fTS156
5946
2009

M/fiche
10193

ACKNOWLEDGEMENTS

In the name of Allah s.w.t, The Most Gracious and Most Merciful, I would like to take this opportunity to thank my supervisor, Associate Professor Michael Khoo Boon Chong for his invaluable guidance, advice and supervision throughout my study and preparation in completing this dissertation. I am certainly unable to complete this task without his assistance.

I am also indebted to the library of Universiti Sains Malaysia for providing me with related reference books and journals. Thanks to everyone who has helped me directly or indirectly throughout my research. Your assistance rendered to me will always be treasured in my heart.

I would also like to extend my full gratitude to my family, friends and the staffs of the School of Mathematical Sciences, Universiti Sains Malaysia for their support and motivation. Thank you very much.

CONTENTS

ACKNOWLEDGEMENTS	ii
CONTENTS	iii
LIST OF TABLES	v
LIST OF FIGURES	vi
ABSTRAK	vii
ABSTRACT	viii

CHAPTER 1: INTRODUCTION

1.1	Quality and Quality Improvement	1
1.2	A brief Discussion on Statistical Quality Control and Improvement	5
1.3	Objectives of the Dissertation	8
1.4	Organization of the Dissertation	9

CHAPTER 2: CONVENTIONAL CONTROL CHART S

2.1	The $\bar{X} - R$ Control Charts	11
2.2	The $\bar{X} - S$ Control Charts	15
2.3	The Moving Average (MA) Control Chart	18

CHAPTER 3: A REVIEW ON SOME ROBUST CONTROL CHARTS

3.1	The Robust $\bar{X}_Q - R_Q$ Charts	21
3.2	The Hodges-Lehmann Control Chart	25

3.3	A Robust Control Chart based on the Hodges-Lehmann and Shamos-Bickel-Lehmann Estimators	28
3.4	The \bar{X}^* and S^* Charts based on Downton's Estimator	31
3.5	The EWMA Control Chart based on Downton's Estimator	36

CHAPTER 4: A PROPOSED ROBUST MOVING AVERAGE CONTROL

CHART

4.1	Introduction	44
4.2	Outliers and their Causes	45
4.3	A Proposed MA_{IQR} Chart	48
4.4	Evaluating the Performance of the MA_{IQR} Chart	49
4.5	An Example of Application	57
4.6	Discussion	61

CHAPTER 5: CONCLUSION

5.1	Introduction	62
5.2	Contributions of the Dissertation	62
5.3	Areas for Further Research	63
5.4	Conclusion	64

REFERENCES	65
-------------------	-----------

APPENDICES

Appendix A	67
Appendix B	68

LIST OF TABLES

		Pages
Table 3.1	Factors for Robust \bar{X}_Q and R_Q Charts	25
Table 3.2	Confidence Levels Associated with Walsh Averages for Selected Sample Sizes	28
Table 3.3	Control Limit Factors for the Proposed Method	32
Table 3.4	Control Limit Constants for the \bar{X}^* Chart	35
Table 3.5	Factors of Control Limits for the EWMAMD Chart, K_1	40
Table 3.6	Factors of Control Limits for the EWMAVD Chart, K_2	41
Table 3.7	Factors of Control Limits for the EWMAVD Chart, K_3	42
Table 4.1	Factors of Control Limits, H_1 for the MA_{IQR} Chart	50
Table 4.2	Signal proportions for two location charting methods based on Four Different situations when $n = 5$	54
Table 4.3	Signal proportions for two location charting methods based on Four Different situations when $n = 7$	55
Table 4.4	Signal proportions for two location charting methods based on Four Different situations when $n = 10$	56
Table 4.5	The Computed Sample Means, Ranges, Interquartile Ranges and the Moving Average Statistics for the Yarn Count Data	58
Table 4.6	Control Limits of the Robust and Standard Moving Average Charts for the Yarn Count Data	58
Table A.1	Factors for Constructing Variables Control Charts	67

LIST OF FIGURES

Figure 1.1	The Meaning of SQC	6
Figure 4.1	A MA Chart with $w = 2$ for the Yarn Count Data	59
Figure 4.2	A MA _{IQR} Chart with $w = 2$ for the Yarn Count Data	59
Figure 4.3	A MA Chart with $w = 5$ for the Yarn Count Data	60
Figure 4.4	A MA _{IQR} Chart with $w = 5$ for the Yarn Count Data	60

CARTA KAWALAN PURATA BERGERAK UNTUK MIN SAMPEL BERDASARKAN SUATU PENGANGGAR SKALA YANG TEGUH

ABSTRAK

Kebelakangan ini, penggunaan carta-carta kawalan kualiti kian bertambah penting. Banyak industri telah meningkatkan penekanan dalam penggunaan carta-carta kawalan, seperti carta-carta Shewhart untuk kawalan proses pengeluaran. Walau bagaimanapun, dalam bidang ini, masih terdapat banyak aspek yang perlu diperluaskan, diselidik secara keseluruhan dan ditambahbaik. Carta-carta kawalan Shewhart tradisional adalah mudah dipengaruhi oleh cerapan-cerapan terpencil yang berlaku sekali-sekala dan muncul secara semulajadi dalam sesuatu proses. Had-had kawalan carta-carta ini adalah mudah diregangkan oleh kehadiran cerapan-cerapan terpencil yang menjadikan carta-carta tersebut tidak peka dalam pengesanan sebarang isyarat luar kawalan. Suatu carta kawalan teguh purata bergerak (MA_{IQR}) akan dicadangkan dalam disertasi ini untuk mengatasi masalah ini. Prestasi carta yang dicadangkan akan dibandingkan dengan prestasi carta konvensional purata bergerak (MA) untuk min proses dengan menggunakan suatu kajian simulasi. Carta kawalan purata bergerak merupakan carta berpemberatkan masa yang berdasarkan purata bergerak yang mudah tanpa pemberat yang diminati. Kajian simulasi menunjukkan bahawa carta kawalan MA_{IQR} yang dicadangkan memberikan keputusan yang lebih baik daripada carta MA konvensional dalam pengesanan cerapan-cerapan terpencil dan situasi luar kawalan lain apabila cerapan-cerapan terpencil hadir.

ABSTRACT

Lately, the use of quality control charts is becoming more important. Many industries have given increased emphasis on using control charts, such as the Shewhart charts in the monitoring of manufacturing processes. In this area, however, there are still many aspects that need to be extended, generalized and improved upon. The traditional Shewhart control charts are easily affected by occasional outliers that might be a natural part of a process. The limits of these charts are easily stretched by the presence of outliers, making them insensitive in the detection of any out-of-control signal. A robust moving average (MA_{IQR}) chart will be proposed in this dissertation to overcome this problem. The performance of the proposed chart is compared with that of the conventional moving average (MA) chart for the process mean using a simulation study. A moving average control chart is a time weighted chart based on a simple, unweighted moving average of interest, where the chart's statistics incorporates past sample points. The simulation study shows that the proposed MA_{IQR} control chart provides superior results to that of the conventional MA chart in the detection of outliers and other forms of out-of-control situations when outliers are present.

CHAPTER 1

INTRODUCTION

1.1 Quality and Quality Improvement

Quality can be defined in many ways, ranging from “satisfying customers’ requirements” to “fitness for use” and “conformance to requirement”. It is obvious that any definition of quality should include customer satisfaction which is the primary goal of any business. In almost all cases, most people have a conceptual understanding of quality as relating to one or more desirable characteristics that a product or service should possess (Montgomery, 2005).

Quality is the overall features and characteristics of a product or service that bear on its ability to satisfy given needs. This definition is the consensus definition in the ANSI/ASQC Standard A3 (1978), a document that provides a comprehensive discussion of quality and related terms. Quality can affect other vital elements of a company such as productivity, cost, delivery schedules, and skills and expertise of the employees including management. It may also have an effect on the workplace environment. Quality also leaves its imprint on society in terms of health, education, cultural and moral values (Montgomery, 2005).

One of the most important consumer decision factors in the selection among competing products and services is quality. The phenomenon is widespread, regardless of whether the consumer is an individual, an industrial organization, a retail store or a military

defense program. As a result, the key factor leading to business success, growth and an enhanced competitive position is to understand and improve the quality of a product.

Garvin (1987) provides an excellent discussion of eight components or dimensions of quality in order to differentiate the quality of a product. In accordance with Garvin, the components of quality can be summarized as follow:

(i) Performance

Customers usually evaluate the ability of a product to function properly. For example, customers evaluate spreadsheet software packages for a PC to determine the data manipulation operations they perform. Customers will be more agreeable with a particular product if it outperforms the other competing products.

(ii) Reliability

The reliability of an item is the probability that it will adequately perform its specified purpose for a specified period of time under specified environmental conditions. For example, an automobile will requires occasional repairs, but if it requires frequent repairs, then it is unreliable.

(iii) Durability

This component indicates the effective service life of a product which is very important to most customers. Customers always want products that perform satisfactorily over a long period of time.

(iv) Serviceability

A customer's view of quality is directly influenced by how quickly and economically a repair or routine maintenance activity can be accomplished. Examples include the appliance and automobile industries and the various types of service industries.

(v) Aesthetics

The outlook of a product such as style, colour, shape, packaging alternatives, tactile characteristics, and other sensory features are important in order to differentiate a product with its competitors.

(vi) Features

Customers always have high expectations with the function of a product, that is, those that have additional features beyond the basic performance of the product. For example, a spreadsheet software package is said to have superior quality if it has built-in statistical analysis features while its competitors do not.

(vii) Perceived Quality

Usually, customers rely on the past reputation of a company concerning the quality of its products. For example, if customers make regular business trips using a particular airline, where the flights almost always arrive on time and that the airline company does not lose or damage any luggage, such customers will probably prefer to fly on the same airlines.

(viii) Conformance to Standards

A high-quality product always meets a customer's requirement. For example, how well does a hood fit on a new car is a measure of conformance to standards.

Many of today's problem solving and quality tools such as control charts, acceptance sampling, process capability analysis and value analysis (VA) were first used extensively in World War II in response to the needs for tremendous volumes of high quality and lower cost materials. More recently, Quality Circles, TQM, and Kaizen have demonstrated the power of team-based process improvement. Process capability and design of experiments (DOE) have come to the fore in Six Sigma (Breckner, 2001).

Quality control should be considered to be more than a set of principles and techniques. It is concerned with using the principles and techniques to achieve the benefits of improved quality, reduced costs, less waste, greater productivity, better deliveries, better marketability and customer acceptance. When a proper attitude and desire have been developed and communicated throughout the enterprise, and quality planning is being carried out, consideration of the latter two categories (quality improvement and quality control) at the process level will assist implementation and achieve positive results.

Quality improvement and quality control are two aspects of quality that are closely related. There is no general rule concerning which should be applied or emphasized first. It varies with the process, product, or service. Applying the procedures to achieve

control of quality may reveal places where improvements of quality are needed. On the other hand, application of techniques to improve quality will often indicate where procedures of control are necessary and beneficial.

1.2 A Brief Discussion on Statistical Quality Control and Improvement

Statistical quality control is defined as the application of statistical methods to measure and analyze the output of a process. Statistical quality control, SQC is the use of statistical techniques to control or improve the quality of the output of some production and service processes. Figure 1.1 illustrates the meaning of SQC.

Statistical techniques provide the facts that indicate how a process has performed in the past, how it is performing currently, and make predictions on its future performance. Thus, SQC provides the basis for actions required in improving process performance and satisfying customer needs (Garrity, 1993).

The use of SQC can be summarized as follow (Garrity, 1993):

- a) Reduce and eliminate errors, scrap and rework in the process.
- b) Improve communication throughout the entire organization.
- c) Encourage active participation in quality improvement.
- d) Increase involvement in the decision-making process.
- e) Simplify and improve work procedures.
- f) Manage the process by facts and not opinion.




Figure 1.1 The Meaning of SQC

Statistical quality control, SQC for repetitive, high volume production began in the 1930's when Shewhart developed control charts. Small production samples were measured periodically to monitor quality. The sample mean (\bar{X}) and sample range (R) charts are used to detect out-of-control points in a process.

The causes of variations which make a sample point to plot beyond the upper and lower control limits must be eliminated in order to bring a process back into statistical control.

Most of the statistical quality control techniques used now have been developed during the last century. One of the most commonly used statistical tools, i.e., a control chart was introduced by Dr. Walter Shewhart in 1924 at the Bell Laboratories. The acceptance sampling techniques were developed by Dr. H. F. Dodge and H. G. Romig in 1928, also at the Bell Laboratories. Design of experiments, developed by Dr. R. A. Fisher in U.K.

is used since in the 1930s. The end of World War II saw an increased interest in quality, primarily among the industries in Japan. This was mainly due to the efforts of Dr. W. E. Deming. Since the beginning of 1980s, U.S. industries have strived to improve the quality of their products. They have been assisted in this endeavour by Dr. Genichi Taguchi, Philip Crosby, Dr. Deming, and Dr. Joseph M. Juran. Industries in the 1980s also benefited from the contributions of Dr. Taguchi on designs of experiments, loss functions, and robust designs. The recent emphasis on teamwork in design has resulted in concurrent engineering. The standards for a quality system, ISO 9000, were later modified and enhanced substantially by the U.S. automobile industries, resulting in QS-9000 (Montgomery, 2005).

The seven major SQC problem solving tools, known as the “Magnificent Seven” are as follow (Montgomery, 2005):

1. **Flow chart:** The whole process is diagrammed from start to finish with each step of the process clearly indicated. Everyone involved in the process should know their positions on the flow chart and at least a partial upstream and downstream trace from their positions.
2. **Pareto chart:** The numbers of occurrences of specific problems are charted on a bar graph. The longer bars indicate the major problems. A Pareto chart is used to determine the priorities in problem solving.
3. **Check sheet:** A data-gathering sheet that categorizes problems or defects. The information of a check sheet may be put on a Pareto chart or, if a time analysis is included, may be used to investigate problem trends over time.

4. **Cause-and-effect diagram:** A problem (the effect) is systematically tracked back to possible causes of the problem. The diagram organizes the search for the root cause of the problem.

5. **Histogram:** A bar graph shows the comparative frequency of specific measurements. The shape of the histogram can indicate that a problem exists at a specific point in a process.

6. **Control chart:** A broken-line graph that illustrates how a process or a point in a process behaves over time. Samples are periodically taken, checked, or measured, and the results plotted on the chart. The charts can show how the specific measurement changes, how the variation in a measurement changes, or how the proportion of defective pieces changes over time.

7. **Scatter plot:** Pairs of measurements are plotted on a two-dimensional coordinate system to determine if a relationship exists between the measurements.

1.3 Objectives of the Dissertation

The objectives of the dissertation are to identify the shortcomings of the moving average control chart for the mean when outliers are present and to propose a robust moving average control chart based on the sample interquartile range (IQR) estimator to overcome the shortcomings of the standard moving average control chart when outliers are present.

1.4 Organization of the Dissertation

This section discusses the organization of the dissertation. Chapter 1 gives the definition of quality and quality improvement, and a brief discussion on statistical quality control and improvement. We also discuss the objectives of this dissertation in this chapter.

Chapter 2 explains the conventional control charts such as the $\bar{X} - R$, $\bar{X} - S$ and moving average (MA) control charts which are among the most important and useful on-line statistical quality control techniques.

Some existing robust control charts will be reviewed in Chapter 3. The purpose of this chapter is to present the existing methods or techniques that solve the problems faced by conventional control charts when outliers are present.

Chapter 4 is the most important part of this dissertation. It discusses the proposed robust moving average control chart. The proposed MA_{IQR} chart is applicable for any sample size. The statistics that are used in the construction of the proposed chart will also be given. The simulation results, in terms of the proportions of signaling an out-of-control signal under different situations are also given and compared with that of the standard moving average chart. Besides, the definition of outliers will also be given in this chapter.

Chapter 5 concludes the research conducted in this dissertation. The contributions of the dissertation will be highlighted. Topics for further research will also be identified in this chapter.

CHAPTER 2

CONVENTIONAL VARIABLES CONTROL CHARTS

2.1 The \bar{X} -R Control Charts

Assume that a quality characteristic is normally distributed with a known mean μ and standard deviation σ . If X_1, X_2, \dots, X_n is a sample of size n , then the average of this sample is

$$\bar{X} = \frac{X_1 + X_2 + \dots + X_n}{n} \quad (2.1)$$

and we know that \bar{X} is normally distributed with mean μ and standard deviation

$\sigma_{\bar{X}} = \frac{\sigma}{\sqrt{n}}$. The probability that a sample mean falls between the limits of the \bar{X} chart,

i.e.,

$$\text{UCL} = \mu + Z_{\alpha/2} \sigma_{\bar{X}} = \mu + Z_{\alpha/2} \frac{\sigma}{\sqrt{n}} \quad (2.2a)$$

and

$$\text{LCL} = \mu - Z_{\alpha/2} \sigma_{\bar{X}} = \mu - Z_{\alpha/2} \frac{\sigma}{\sqrt{n}} \quad (2.2b)$$

is $1 - \alpha$ (Montgomery, 2005).

Therefore, if the mean μ and standard deviation σ are known, Equations (2.2a) and (2.2b) could be used as the upper control limit (UCL) and lower control limit (LCL), respectively. It is customary to replace $Z_{\alpha/2}$ by 3, so that the three-sigma limits are employed. If a sample mean falls outside of these limits, it is an indication that the

process mean is no longer equal to μ . Here, we assume that the distribution of the quality characteristic is normal. However, the above results are still approximately correct even if the underlying distribution is slightly nonnormal because of the central limit theorem.

In practice, usually both μ and σ are unknown. Therefore, we must estimate these parameters from a preliminary data set or subgroups taken when the process is thought to be in-control. These estimates are usually based on at least 20 to 25 samples.

Suppose that m samples are available, each containing n observations on the quality characteristic. The sample size, n is usually small having a value of 4, 5 or 6. The sample size is small so that we can reduce the cost of sampling and inspection (Montgomery, 2005).

Let $\bar{X}_1, \bar{X}_2, \dots, \bar{X}_m$ be the sample mean for each of the m samples, then the best estimator of μ is

$$\bar{\bar{X}} = \frac{\bar{X}_1 + \bar{X}_2 + \dots + \bar{X}_m}{m}. \quad (2.3)$$

Here, $\bar{\bar{X}}$ is used as the center line (CL) of the control chart.

Let X_1, X_2, \dots, X_n be a sample of size n , then the range of the sample is the difference between the largest and the smallest observations, i.e.,

$$R = X_{\max} - X_{\min} \quad (2.4)$$

$$\text{Let } \bar{R} = \frac{R_1 + R_2 + \dots + R_m}{m} \quad (2.5)$$

be the average range of these m sample ranges.

An estimator of σ can be obtained as

$$\hat{\sigma} = \frac{\bar{R}}{d_2}, \quad (2.6)$$

where the value d_2 depends on the sample size, n . Values of d_2 for the various sample sizes are given in Table A.1 in Appendix A.

If \bar{X} is an estimator of μ and $\frac{\bar{R}}{d_2}$ is an estimator of σ , then the limits for the \bar{X} chart

are

$$\text{UCL}_{\bar{X}} = \bar{X} + \frac{3}{d_2\sqrt{n}}\bar{R} \quad (2.7a)$$

$$\text{CL}_{\bar{X}} = \bar{X} \quad (2.7b)$$

$$\text{LCL}_{\bar{X}} = \bar{X} - \frac{3}{d_2\sqrt{n}}\bar{R} \quad (2.7c)$$

If $A_2 = \frac{3}{d_2\sqrt{n}}$, then Equations (2.7a), (2.7b) and (2.7c) can be written as

$$\text{UCL}_{\bar{X}} = \bar{X} + A_2\bar{R} \quad (2.8a)$$

$$\text{CL}_{\bar{X}} = \bar{X} \quad (2.8b)$$

$$\text{LCL}_{\bar{X}} = \bar{X} - A_2\bar{R} \quad (2.8c)$$

Values of A_2 for the various sample sizes are given in Table A.1 in Appendix A.

Now, we consider the control limits for the R chart. The center line for the R chart is \bar{R} .

We need an estimator of σ_R to determine the control limits when μ and σ are unknown.

σ_R can be found from the distribution of the relative range $W = R/\sigma$. The standard deviation of W is d_3 (Montgomery, 2005).

Since,

$$R = W\sigma, \quad (2.9)$$

the standard deviation of R is

$$\sigma_R = d_3\sigma, \quad (2.10)$$

where the values of d_3 for various sample sizes, n are given in Table A.1 in Appendix A.

If σ is unknown, it can be estimated by $\hat{\sigma} = \frac{\bar{R}}{d_2}$. Thus,

$$\hat{\sigma}_R = d_3 \frac{\bar{R}}{d_2}. \quad (2.11)$$

Consequently, the control limits of the R chart are

$$\text{UCL}_R = \bar{R} + 3\hat{\sigma}_R = \bar{R} + 3d_3 \frac{\bar{R}}{d_2} \quad (2.12a)$$

$$\text{CL}_R = \bar{R} \quad (2.12b)$$

$$\text{LCL}_R = \bar{R} - 3\hat{\sigma}_R = \bar{R} - 3d_3 \frac{\bar{R}}{d_2} \quad (2.12c)$$

Let $D_3 = 1 - 3\frac{d_3}{d_2}$ and $D_4 = 1 + 3\frac{d_3}{d_2}$.

Equations (2.12a), (2.12b) and (2.12c) can be written as

$$\text{UCL}_R = D_4 \bar{R} \quad (2.13a)$$

$$\text{CL}_R = \bar{R} \quad (2.13b)$$

$$\text{LCL}_R = D_3 \bar{R} \quad (2.13c)$$

The values of D_3 and D_4 for various sample sizes, n are given in Table A.1 in Appendix A. The R chart is plotted first to determine if the process variance is stable before the \bar{X} chart is plotted.

2.2 The $\bar{X} - S$ Control Charts

The S control chart uses the sample standard deviation, S , to monitor changes in the process variance. Banks (1989) recommended the use of the S control chart instead of the R chart to monitor process dispersion for larger sample sizes ($n > 10$) and when sample sizes, n are unequal. The sample mean, \bar{X} and sample standard deviation, S are used in the construction of the $\bar{X} - S$ charts. If σ^2 is unknown, then an unbiased estimator of σ^2 is the sample variance

$$S^2 = \frac{\sum_{i=1}^n (X_i - \bar{X})^2}{n-1} = \frac{\sum_{i=1}^n X_i^2 - n\bar{X}^2}{n-1}. \quad (2.14)$$

However, the sample standard deviation, S is not an unbiased estimator of σ , that is $E(S) \neq \sigma$.

Assuming that the underlying distribution is normal, then the mean and the standard deviation of S are (Banks, 1989)

$$E(S) = c_4 \sigma \quad (2.15)$$

and

$$\sigma_s = \sigma \sqrt{1 - c_4^2}, \quad (2.16)$$

respectively, where the values of c_4 for the various sample sizes, n are given in Table A.1 in Appendix A.

The three-sigma limits of the S chart if the standard deviation of the underlying process, σ is known are as follow (Montgomery, 2005):

$$UCL_S = c_4 \sigma + 3\sigma \sqrt{1 - c_4^2} = B_6 \sigma \quad (2.17a)$$

$$CL_S = c_4 \sigma \quad (2.17b)$$

$$LCL_S = c_4 \sigma - 3\sigma \sqrt{1 - c_4^2} = B_5 \sigma \quad (2.17c)$$

It is customary to define the two constants $B_6 = c_4 + 3\sqrt{1 - c_4^2}$ and $B_5 = c_4 - 3\sqrt{1 - c_4^2}$.

Values of B_5 and B_6 for various sample sizes are given in Table A.1 in Appendix A. If

the value of σ is unknown, then it must be estimated from past data. Assume that m preliminary subgroups are available, each of size n . Let S_i be the standard deviation of the i th sample. The average of the m standard deviations is

$$\bar{S} = \frac{1}{m} \sum_{i=1}^m S_i . \quad (2.18)$$

If the standard deviation of the population, σ is unknown, then the estimate of σ is \bar{S}/c_4 .

The three-sigma limits of the S chart are

$$UCL_S = \bar{S} + 3 \frac{\bar{S}}{c_4} \sqrt{1 - c_4^2} = B_4 \bar{S} \quad (2.19a)$$

$$CL_S = \bar{S} \quad (2.19b)$$

$$LCL_S = \bar{S} - 3 \frac{\bar{S}}{c_4} \sqrt{1 - c_4^2} = B_3 \bar{S}, \quad (2.19c)$$

where $B_3 = 1 - \frac{3}{c_4} \sqrt{1 - c_4^2}$ and $B_4 = 1 + \frac{3}{c_4} \sqrt{1 - c_4^2}$.

The control limits of the \bar{X} control chart are computed from the following formulae:

$$UCL_{\bar{X}} = \bar{\bar{X}} + \frac{3}{c_4 \sqrt{n}} \bar{S} = \bar{\bar{X}} + A_3 \bar{S} \quad (2.20a)$$

$$CL_{\bar{X}} = \bar{\bar{X}} \quad (2.20b)$$

$$LCL_{\bar{X}} = \bar{\bar{X}} - \frac{3}{c_4 \sqrt{n}} \bar{S} = \bar{\bar{X}} - A_3 \bar{S}, \quad (2.20c)$$

where $A_3 = \frac{3}{c_4 \sqrt{n}}$. Values of constants A_3 , B_3 and B_4 for various sample sizes, n are

given in Table A.1 in Appendix A.

2.3 The Moving Average (MA) Control Chart

The MA chart is a weighted chart which is based on simple and unweighted moving averages.

Assume that samples of size n have been collected. Let $\bar{X}_1, \bar{X}_2, \dots, \bar{X}_t$ denote the corresponding sample means. The moving average of span w at time t is defined as (Montgomery, 2005)

$$M_t = \frac{\bar{X}_t + \bar{X}_{t-1} + \dots + \bar{X}_{t-w+1}}{w}$$

$$= \frac{\sum_{j=t-w+1}^t \bar{X}_j}{w}, t \geq w \quad (2.21)$$

The moving average statistic of width w is simply the average of the w most recent sample means. For periods $t < w$, since we do not have w sample means yet, the average of all sample means up to period t defines the moving average. For example, if $w = 3$, we have

$$M_1 = \frac{\bar{X}_1}{1} \quad (2.22a)$$

$$M_2 = \frac{\bar{X}_1 + \bar{X}_2}{2} \quad (2.22b)$$

and

$$M_t = \frac{\bar{X}_t + \bar{X}_{t-1} + \bar{X}_{t-2}}{3}, t \geq 3. \quad (2.22c)$$

At time t , the moving average is updated by dropping the oldest sample mean and the newest one is added to the set. The variance of the moving average statistic M_t is

$$Var(M_t) = \frac{1}{w^2} Var(\bar{X}_t + \bar{X}_{t-1} + \dots + \bar{X}_{t-w+1}). \quad (2.23)$$

If \bar{X}_t is the t th sample mean, then

$$Var(\bar{X}_t) = Var(\bar{X}) = \frac{\sigma^2}{n}. \quad (2.24)$$

Thus,

$$Var(M_t) = \frac{1}{w^2} \sum_{i=t-w+1}^t \frac{\sigma^2}{n} = \frac{\sigma^2}{nw} \quad (2.25)$$

and the standard deviation of M_t is $\sigma_{M_t} = \sigma / \sqrt{nw}$.

The three-sigma control limits for the moving average chart are

$$UCL_{M_t} = \bar{\bar{X}} + \frac{3\sigma}{\sqrt{nw}} \quad (2.26a)$$

$$CL_{M_t} = \bar{\bar{X}} \quad (2.26b)$$

$$LCL_{M_t} = \bar{\bar{X}} - \frac{3\sigma}{\sqrt{nw}}, \quad (2.26c)$$

where n denotes the sample size. Note that for period $t < w$, w is replaced with t in Equations (2.26a) and (2.26c).

If the value of σ is unknown, it can be replaced with $\hat{\sigma} = \bar{R}/d_2$ or $\hat{\sigma} = \bar{S}/c_4$, where \bar{R} and \bar{S} denote the average sample range and average sample standard deviation, respectively, both estimated from an in-control historical data set. In practice, \bar{R} is considered for $n < 10$ while \bar{S} otherwise (Montgomery, 2005).

In general, the magnitude of a shift of interest and w are inversely related, i.e., smaller shifts would be guarded against more effectively by longer-span moving average, w , at the expense of a quick response to large shifts (Montgomery, 2005).

CHAPTER 3

A REVIEW ON SOME ROBUST CONTROL CHARTS

3.1 The Robust $\bar{X}_q - R_q$ Charts

When a process is first subjected to statistical quality control, a normal procedure is to collect 20-40 subgroups of observations and then to construct control charts such as \bar{X} and R charts with limits determined by the data. These control charts are then used to detect problems in the process, such as outliers or excessive variability in the sample means that may be due to a special cause. Rocke (1989 and 1992) proposed a new method of determining the control limits for \bar{X} and R charts that result in easier detection of outliers and greater sensitivity to other forms of out-of-control behavior when outliers are present. The control limits for these charts, i.e., the \bar{X}_q and R_q charts are determined from the average subgroup interquartile range.

This new charting method will be appropriate when the following conditions are satisfied (Rocke, 1992):

- 1) The control limits are to be established from the data at hand, rather than from a known value of σ , the process standard deviation. This will usually be the case when a process is newly brought under statistical quality control procedures.
- 2) There is a possibility of outliers in the data within the subgroup. If the distribution is known to be normal (which would rarely be the case), then standard procedures such as \bar{X} and R charts will suffice. The terms 'outlier' is used to mean an observation that is unusually far from the rest of the data. This may indicate that the particular

data point was drawn from a different population or that a sporadic special cause was operating.

The \bar{X}_Q chart is a chart of subgroup means, in which the control limits are set using an estimate of the process standard deviation based on the average of the subgroup interquartile ranges (IQRs) rather than the average of the subgroup ranges.

The interquartile range, IQR is defined as $X_{(b)} - X_{(a)}$, where () denotes the order statistics $a = [n/4] + 1$ and $b = n - a + 1$. Here, $[x]$ represents the greatest integer that is less than or equal to x . The mathematical expectation of IQR can be defined as (Rocke, 1992)

$$E(\text{IQR}) = d_2^Q \sigma, \quad (3.1)$$

where d_2^Q is a constant whose value depends on the sample size, n (see Table 3.1).

Then, we may estimate the standard deviation, σ by

$$\sigma_Q = \frac{\overline{\text{IQR}}}{d_2^Q}, \quad (3.2)$$

where $\overline{\text{IQR}}$ is the average of the subgroup interquartile ranges.

The control limits for the \bar{X}_Q chart are as follow (Rocke, 1992):

$$\text{UCL}_{\bar{x}_Q} = \bar{X} + 3 \frac{\hat{\sigma}_Q}{\sqrt{n}}$$

$$= \bar{X} + 3 \frac{\overline{\text{IQR}}}{(d_2^o \sqrt{n})} \quad (3.3a)$$

$$\text{CL}_{\bar{x}_o} = \bar{X} \quad (3.3b)$$

$$\begin{aligned} \text{LCL}_{\bar{x}_o} &= \bar{X} - 3 \frac{\hat{\sigma}_o}{\sqrt{n}} \\ &= \bar{X} - 3 \frac{\overline{\text{IQR}}}{(d_2^o \sqrt{n})} \end{aligned} \quad (3.3c)$$

If $A_2^o = \frac{3}{(d_2^o \sqrt{n})}$, then Equations (3.3a), (3.3b) and (3.3c) can be written as

$$\text{UCL}_{\bar{x}_o} = \bar{X} + A_2^o \overline{\text{IQR}} \quad (3.4a)$$

$$\text{CL}_{\bar{x}_o} = \bar{X} \quad (3.4b)$$

$$\text{LCL}_{\bar{x}_o} = \bar{X} - A_2^o \overline{\text{IQR}}. \quad (3.4c)$$

Values of d_2^o and A_2^o for the various sample sizes, n are given in Table 3.1.

The R_o chart is a chart of subgroup ranges in which the control limits again, for the sake of robustness to outliers, are set using the IQR. For normal distributions

$$E(R) = d_2 \sigma, \quad (3.5)$$

$$E(\text{IQR}) = d_2^o \sigma \quad (3.6)$$

and

$$\text{SD}(R) = d_3 \sigma. \quad (3.7)$$

Then the control limits for the R_o chart are computed as follows (Rocke, 1992):

$$UCL_{R_Q} = d_2 \frac{\overline{IQR}}{d_2^Q} + 3d_3 \frac{\overline{IQR}}{d_2^Q} \quad (3.8a)$$

$$CL_{R_Q} = d_2 \frac{\overline{IQR}}{d_2^Q} \quad (3.8b)$$

$$LCL_{R_Q} = d_2 \frac{\overline{IQR}}{d_2^Q} - 3d_3 \frac{\overline{IQR}}{d_2^Q}, \quad (3.8c)$$

where d_2 and d_3 are standard constants (Wadsworth et al., 1986).

Let

$$d_2^{QR} = \frac{d_2}{d_2^Q}, \quad (3.9)$$

$$D_3^Q = \max \{0, (d_2 - 3d_3) / d_2^Q\} \quad (3.10)$$

and

$$D_4^Q = (d_2 + 3d_3) / d_2^Q, \quad (3.11)$$

then the control limits for the R_Q chart can be written as (Rocke, 1992)

$$UCL_{R_Q} = D_4^Q \overline{IQR} \quad (3.12a)$$

$$CL_{R_Q} = d_2^{QR} \overline{IQR} \quad (3.12b)$$

$$LCL_{R_Q} = D_3^Q \overline{IQR}. \quad (3.12c)$$

Values of d_2^{QR} , D_3^Q and D_4^Q for the various sample sizes are given in Table 3.1.