

**THE EFFECTS OF CHANGES AT SIGNALIZED
INTERSECTION ON THE VEHICLES EMISSION
LOADING IN PARIT BUNTAR, PERAK.**

By

MAISARAH BT SULAIMAN

Dissertation submitted in fulfilment of the requirements
for the degree of
Master of Science (Environmental Engineering)

**School of Civil Engineering
Universiti Sains Malaysia**

June 2011

ACKNOWLEDGEMENT

In the name of Allah, all praise is due to Him, the Sustainer of the Heaven and Earth and all that is within it and may His blessings be upon the Prophet Muhammad, peace be upon him. Alhamdulillah, with the grace and blessings of Allah, I have finally finished my thesis.

First and foremost, I would like to thank to my supervisor, Associates Professor Nor Azam bin Ramli. I am grateful for the support, time, guidance, advice and all the help and knowledge given and shared by him in order to finish this research. Your patience in enduring my occasional procrastinating and mistakes is highly appreciated and will never be forgotten. Furthermore, I would like to thank Universiti Sains Malaysia especially School of Civil Engineering. It provides me the chance of studying on this research and all the facilities that I used in order to do this study.

Next, I would like to take this opportunity to thank Nor Salmi and Siti Hajar that render me help in traffic count for two months in order to finish the thesis. I also thank for them to give me support during this period.

For my family, first and foremost this thesis is special dedicated to my Abah and Mak who really want me to pursue this Master Degree. Without your determination and support I will never come this far. Whatever I have done throughout this journey is only for you.

To anyone whom I have forgotten, your help is very appreciated and only Allah can repay all your kindness. Sincerely thanks from me to all nameless and faceless people who have HELP me along the way.

ABSTRACT

The transportation in Peninsular Malaysia includes public transport such as buses and trains and private transport such as motorcycles and cars. The emissions of Carbon Dioxide (CO_2) and Oxides of Sulphur (SO_x) vary directly with fuel consumption. The emissions of Carbon Monoxide (CO), Oxides Of Nitrogen (NO_x), Particulate Matter and Hydrocarbons vary in addition with the engine design, the air-to-fuel ratio, and vehicle operating characteristics, with an optimum speed usually in excess of 60 kilometres (km) per hour. At the signalized intersection, the amount of traffic emission are depend on the four mode elemental driving cycle consisting of cruise, acceleration, deceleration and idling time for specific traffic condition represented by traffic flow, traffic control and intersection geometry. The signalized intersection that designed according to the proper standard will minimize delay and optimize the junction capacity while the improper design geometry will increase the delay faced by road users. SIDRA Intersection 5.1 software was used in this study in order to investigate the vehicles emissions due to traffic volume and its delay time and the effect of traffic light junction's configuration during peak hour. There are six signalized intersection along the major road of Jalan Taiping and Jalan Abdul Raof in Parit Buntar will be investigated. The vehicles emission pollution that carried out for year 2010 were generated and compared with the current study in year 2011. Some improvement was proposed in this study in term of coordination between adjacent signal light controllers, left turn on red movement, providing proper signal phasing and signal time and minor geometrical modifications at the chosen signalized intersections. The result for each signalized intersection showed the significant reduction in the amount of vehicles emissions and average delay time. For signalized intersection between Jalan Taiping, Jalan Padang, and Jalan Lintang the percent of

reduction for fuel consumption, hydrocarbon, oxides of nitrogen and carbon dioxide approximately 42 % due to the reduction of delay time approximately 23% after the implementing minor geometry and signal phasing. Total fuel reduction for signalized intersection between Jalan Taiping and diversion from Shell petrol Station and signalized intersection between Jalan Abdul Raof and diversion Shell petrol Station showed the reduction in approximately 12% and 6% after the implementation of the signal time modification. Other than that, the reduction of fuel consumption at Jalan Taiping and Jalan perusahaan 17% after the implementation of the minor geometry and signal phasing modification. Lastly, reduction in fuel consumption and hydrocarbon more than 43 % compared to the hydrocarbon emissions in year 2010 at Jalan Taiping and Federal Route 1.

ABSTRAK

Pengangkutan utama di Semenanjung Malaysia terdiri daripada pengangkutan awam seperti bas dan kereta api dan pengangkutan persendirian seperti kereta dan motorsikal. Pembebasan karbon dioksida (CO_2) dan oksida sulfur (SO_x) berubah – ubah secara langsung dengan penggunaan bahan bakar. Pembebasan karbon monoksida (CO), oksida nitrogen (NO_x), zarah halus dan hidrokarbon berubah-ubah berdasarkan reka cipta enjin, nisbah udara ke bahan bakar, dan ciri – ciri operasi kenderaan dengan kelajuan optimum melebihi 60 Kilometer per jam. Di persimpangan bersignal, jumlah pembebasan pencemaran lalu lintas bergantung pada empat kitaran mod memandu yang terdiri daripada unsur berhenti dan menunggu di persimpangan lampu isyarat, pecutan, nyahpecutan halaju kenderaan, dan masa yang digunakan oleh kenderaan untuk tidak bergerak bagi keadaan lalulintas tertentu diwakili oleh arus lalu lintas dan geometri persimpangan. Simpang bersignal yang direka bentuk mengikut piawaian yang ditetapkan akan dapat meminimumkan kelewatan dan mengoptimumkan kapasiti persimpangan sedangkan rekabentuk geometri yang tidak tepat akan meningkatkan kelewatan yang dihadapi oleh pengguna jalan raya. Dalam kajian ini terdapat enam simpang bersignal di sepanjang jalan utama iaitu Jalan Taiping dan Jalan Abdul Raof di Parit Buntar. Pembebasan pencemaran kenderaan yang terhasil untuk tahun 2010 akan dibandingkan dengan kajian semasa 2011. Beberapa penambahbaikan dicadangkan dalam kajian ini seperti koordinasi antara kawalan isyarat yang baik, pergerakan pusing ke kiri semasa lampu merah, menyediakan masa isyarat dan fasa isyarat yang betul dan sedikit penambahbaikan dari segi geometri persimpangan bagi persimpangan bersignal yang dikaji. Keputusan untuk setiap persimpangan bersignal menunjukkan penurunan yang signifikan bagi jumlah pembebasan

pencemaran kendaraan dan kelewatan waktu. Untuk persimpangan bersignal antara Jalan Taiping, Jalan Padang dan Jalan Lintang peratus pengurangan untuk penggunaan bahan bakar, hidrokarbon, nitrogen oksida dan karbon dioksida sekitar 42% dan pengurangan masa kelewatan mencapai sekitar 23% setelah berlakunya perubahan minor geometri dan fasa isyarat. Jumlah pengurangan bahan bakar untuk persimpangan Jalan Taiping dan lencongan dari Stesen Minyak Shell dan persimpangan bersignal antara Jalan Abdul Raof dan lencongan daripada Stesen Minyak Shell menunjukkan pengurangan menghampiri 12% dan 6% selepas penambakan perubahan pada fasa isyarat. Selain itu, pengurangan penggunaan bahan bakar di Jalan Taiping dan Jalan Perusahaan mencapai kepada 17% selepas penambakan minor untuk geometri dan perubahan fasa isyarat. Akhir sekali, di persimpangan Jalan Taiping dan Jalan Persekutuan Utama, pengurangan terhadap penggunaan bahan bakar dan hydrocarbon adalah melebihi 43% berbanding pada tahun 2010.

TABLE OF CONTENTS

	Page
ACKNOWLEDGEMENT	ii
ABSTRACT	iii
ABTRAK	v
TABLE OF CONTENTS	vii
LIST OF FIGURES	xiv
LIST OF PLATES	xxiii
LIST OF TABLES	xxiv
CHAPTER 1 : INTRODUCTION	
1.1 General	1
1.2 Problem Statement	2
1.3 Objectives	3
1.4 Scope of study	3
1.5 Justification of the research	4
1.6 Contents of report	5
CHAPTER 2 : LITERATURE REVIEW	
2.1 Introduction	6
2.2 Vehicles Emission	
2.2.1 Nitrogen Oxides	7
2.2.2 Hydrocarbons and Carbon Monoxide	8
2.2.3 Contribution of Traffic Emissions to Ozone and Oxides of Nitrogen	8

2.3	Factors Affecting Emission Rates	9
2.3.1	Diesel engine	9
2.4	Emission Standard of Pollutants for New Models of Motor Vehicles on or After 1 January 1997	10
2.5	The Malaysian Petrol and Diesel Standards	11
2.6	Atmosphere Effects Of Transport- Related Air	12
2.7	Health Effects Of Transport- Related Air	13
2.7.1	Allergic Illness/ Symptoms Including Asthma	15
2.7.2	Lug Function	16
2.7.3	Cancer	16
2.8	Fuel Consumption	17
2.9	Signalized Intersection and Vehicles Emissions	18
2.10	SIDRA INTERSECTION 5.1 Software	19
2.11	Four Mode Elemental Model Applied in SIDRA INTERSECTION 5.1.	20
2.12	Level of Service	23
2.13	Factors that Affect the Capacity	25
2.14	Terminology And Definition of Intersection	26
2.15	How To Optimize Traffic Emission	28
CHAPTER 3 : METHODOLOGY		
3.1	Introduction	30
3.2	Site Selection	33
3.3	Data Collection	
3.3.1	Traffic Volume Observation	36

3.3.2	Geometry Measurement	39
3.33	Cycle time	40
3.4	Data Analysis	
3.4.1	Passenger Car Unit (PCU)	40
3.5	Input dialogs in SIDRA INTERSECTION Version 5.1	
3.5.1	Intersection	42
3.5.2	Volumes	42
3.5.3	Unit Time for Volumes	42
3.5.4	Saturation Flow	43
3.5.5	Optimum Cycle Time	45
3.5.5.1	Fixed-Time/Pretimed	45
3.5.5.2	Actuated	46
3.6	Fuel Consumption and Emissions	46
3.7	Operating Cost	48
3.8	Delay	50
CHAPTER 4: RESULT AND DISCUSSION		
4.1	Introduction	52
4.2	Signalized Intersection between Jalan Taiping, Jalan Padang and Jalan Lintang.	
4.2.1	Existing Condition	52
4.2.2	Proposed Improvement at Signalized Intersection between Jalan Taiping, Jalan Padang and Jalan Lintang in 2011.	55
4.2.3	Evaluation of Delays and Level of Service after Proposed Improvement at Signalized Intersection between Jalan Taiping, Jalan Padang And Jalan Lintang in 2010 and 2011.	57

4.2.4	Evaluation of Average Fuel Consumption and Average Pollutant Emissions at Signalized Intersection between Jalan Taiping, Jalan Padang and Jalan Lintang in 2010 and 2011.	60
4.2.5	Evaluation of Maximum Fuel Consumption (L/hr) and Maximum Pollutant Emissions (kg/hr) for Each Peak Hours at Signalized Intersection Between Jalan Taiping, Jalan Padang And Jalan Lintang in 2011	63
4.3	Signalized Intersection between Jalan Taiping and Diversion from Shell Petrol Station.	
4.3.1	Existing Condition	65
4.3.2	Evaluation of Delays and Level of Service for Existing and Improve Condition at Signalized Intersection between Jalan Taiping and diversion from SJKC Sin Hwa in 2011.	68
4.3.3	Evaluation of Average Fuel Consumption and Average Pollutant Emissions at Signalized Intersection between Jalan Taiping and Diversion from SJKC Sin Hwa in Existing and Improved Condition in 2011.	70
4.3.4	Evaluation of Maximum Fuel Consumption (L/hr) and Pollutant Emissions (kg/hr) for Each Peak Hours at Signalized Intersection between Jalan Taiping and Diversion from SKJC Sin Hwa in 2011	71
4.4	Signalized Intersection between Jalan Abdul Raof and diversion from SJKC Sin Hwa	
4.4.1	Existing Condition	74
4.4.2	Evaluation of delays and Level of Service for existing and	77

	improve condition at Signalized Intersection Between Jalan Abdul Raof and diversion from SKJC Sin Hwa in 2011.	
4.4.3	Evaluation of Average Fuel Consumption and Pollutant Emissions at Signalized Intersection between Jalan Abdul Raof and Diversion from SKJC Sin Hwa in 2011	78
4.4.4	Evaluation of Maximum Fuel Consumption (L/hr) and Maximum Pollutant Emissions (kg/hr) for Each Peak Hours at Signalized Intersection between Jalan Abdul Raof and Diversion from SKJC Sin Hwa in 2011	80
4.5	Signalized intersection between Jalan Taiping, Jalan Sekolah and Diversion from Bank Islam.	
4.5.1	Existing Condition	83
4.5.2	Evaluation of Delays and Level of Service for Existing and Improve Condition at Signalized Intersection between Jalan Taiping , Jalan Sekolah and Diversion from Bank Islam in 2011	85
4.5.3	Evaluation of Average Fuel Consumption and Average Pollutant Emissions at Signalized Intersection between Jalan Taiping , Jalan Sekolah and Diversion from Bank Islam in 2011	87
4.5.4	Evaluation of Maximum Fuel Consumption (L/hr) and Maximum Pollutant Emissions (kg/hr) for Each Peak Hours at Signalized Intersection Between Jalan Taiping, Jalan Sekolah and diversion from Bank Islam in 2011	88

4.6	Signalized Intersection between Jalan Taiping and Jalan Perusahaan.	
4.6.1	Existing condition	91
4.6.2	Proposed Improvement for Traffic Light Junction at Signalized Intersection Between Jalan Taiping and Jalan Perusahaan in Year 2011.	93
4.6.3	Evaluation of Delays and Level of Service for Existing And Improve Condition at Signalized Intersection Between Jalan Abdul Raof and diversion from SKJC Sin Hwa in 2011.	95
4.6.4	Evaluation of Average Fuel Consumption and Average Pollutant Emissions at Signalized Intersection between Jalan Taiping and Jalan perusahaan in 2010 and 2011.	98
4.6.5	Evaluation of Maximum Fuel Consumption (L/hr) and Maximum Pollutant Emissions (kg/hr) for Each Peak Hours at Signalized Intersection between Jalan Taiping, and Jalan Perusahaan in 2010 and 2011	101
4.7	Signalized Intersection between Jalan Taiping and Federal Route 1	
4.7.1	Existing Condition	
4.7.2	Proposed Improvement at Signalized Intersection between Jalan Taiping and Federal Route 1 in 2011.	104 106
4.7.3	Evaluation of Delays and Level of Service for Existing and Improved Condition at Signalized Intersection between Jalan Taiping and Federal Route 1 in 2011.	108
4.7.4	Evaluation of Average Fuel Consumption and Average Pollutant Emissions at Signalized Intersection between Jalan Taiping and Federal Route 1 in 2010 and 2011	112

4.7.5	Evaluation of Maximum Fuel Consumption (L/hr) and Maximum Pollutant Emissions (kg/hr) for Each Peak Hours at Signalized Intersection Between Jalan Taiping, and Federal Route 1 in 2010 and 2011	114
-------	---	-----

CHAPTER 5: CONCLUSION

5.1	Conclusion	117
5.2	Recommendation for future study	120

REFERENCES

APPENDIX A

PICTURE OF STUDY SITES

LIST OF FIGURES

	Page
Figure 2.1	7
Historical Carbon Oxide emissions from the transportation sector	
Figure 2.2	14
Health benefits from various scenarios with respect to based case scenario in Shanghai in 2010, 2015 and 2020 (Mean and 95% CI).	
Figure 2.3	21
Four mode elemental model used in SIDRA INTERSECTION 5.1 for modelling fuel consumption, pollutant emissions, cost and geometric delay	
Figure 3.1	30
Flow chart of methodology	
Figure 3.2	39
Sample geometric layout for traffic volume observation	
Figure 3.3	41
Operation of the SIDRA Intersection 5.1 systems	
Figure 3.4	50
Definition of delay experienced by a vehicle stopping at traffic signals	
Figure 4.1	53
Schematic geometric layout of the existing condition at intersection between Jalan Taiping, Jalan Lintang and Jalan Padang in 2011.	
Figure 4.2	54
Existing signal phasing for intersection between Jalan Taiping, Jalan Lintang and Jalan Padang in 2011.	
Figure 4.3	56
Schematic layout of the proposed improvement for signalized intersection between Jalan Taiping, Jalan Padang And Jalan Lintang in 2011.	

Figure 4.4	Proposed improvement Signal Phasing at Signalized Intersection between Jalan Taiping, Jalan Padang and Jalan Lintang in 2010 and 2011	57
Figure 4.5	Average fuel consumption and pollutant emissions at signalized intersection between Jalan Taiping, Jalan Padang and Jalan Lintang in 2011.	61
Figure 4.6	Average fuel consumption and pollutant emissions at signalized intersection between Jalan Taiping, Jalan Padang and Jalan Lintang in 2010.	61
Figure 4.7	Average pollutant emissions at signalized intersection between Jalan Taiping, Jalan Padang and Jalan Lintang in 2011	62
Figure 4.8	Average pollutant emissions at signalized intersection between Jalan Taiping, Jalan Padang and Jalan Lintang in 2010	62
Figure 4.9	Existing maximum of fuel consumption (L/hr) for intersection between Jalan Taiping, Jalan Padang and Jalan Lintang in 2011.	63
Figure 4.10	Existing maximum of carbon dioxide emissions (kg/hr) for intersection between Jalan Taiping, Jalan Padang and Jalan Lintang in 2011.	64
Figure 4.11	Existing maximum of carbon monoxide emissions (kg/hr) for intersection between Jalan Taiping, Jalan Padang and Jalan Lintang in 2011.	64

Figure 4.12	Existing maximum of hydrocarbon emissions (kg/hr) for intersection between Jalan Taiping, Jalan Padang and Jalan Lintang in 2011.	64
Figure 4.13	Existing Maximum of oxides of nitrogen emissions (kg/hr) for intersection between Jalan Taiping, Jalan Padang and Jalan Lintang in 2011.	65
Figure 4.14	Schematic geometric layout of the existing condition signalized intersection between Jalan Taiping and diversion from Shell Petrol Station in 2011.	66
Figure 4.15	Existing signal phasing for intersection between Jalan Taiping and diversion from Shell Petrol Station in 2011.	67
Figure 4.16	Average fuel consumption and pollutant emissions at signalized intersection between Jalan Taiping and Diversion from SJKC Sin Hwa in 2011.	70
Figure 4.17	Average pollutant emissions at signalized intersection between Jalan Taiping and Diversion from SJKC Sin Hwa in 2011.	71
Figure 4.18	Existing maximum of fuel consumption (L/hr) for Intersection between Jalan Taiping and Diversion from SJKC Sin Hwa in 2011	72
Figure 4.19	Existing maximum of carbon dioxide emissions (kg/hr) for intersection between Jalan Taiping and Diversion from SKJC Sin Hwa in 2011.	72

Figure 4.20	Existing maximum of carbon oxide emissions (kg/hr) for intersection between Jalan Abdul Raof and diversion from SKJC Sin Hwa in 2011.	72
Figure 4.21	Existing maximum of hydrocarbon emissions (kg/hr) for intersection between Jalan Taiping and Diversion from SKJC Sin Hwa in 2011	73
Figure 4.22	Existing maximum of oxides of nitrogen emissions (kg/hr) for intersection between Jalan Taiping and Diversion from SKJC Sin Hwa in 2011.	73
Figure 4.23	Schematic geometric layout of the existing condition signalized intersection between Jalan Abdul Raof and diversion from SJKC Sin Hwa in 2011.	75
Figure 4.24	Schematic geometric layout of existing signal phasing at signalized intersection between Jalan Abdul Raof and diversion from SKJC Sin Hwa in 2011.	76
Figure 4.25	Average fuel consumption and pollutant emissions at signalized intersection between Jalan Abdul Raof and Diversion from SJKC Sin Hwa in 2011	79
Figure 4.26	Average pollutant emissions at signalized intersection between Jalan Abdul Raof and Diversion from SJKC Sin Hwa in 2011.	79
Figure 4.27	Existing maximum of fuel consumption (L/hr) for intersection between Jalan Abdul Raof and diversion from SJKC Sin Hwa in 2011.	80

Figure 4.28	Existing maximum of carbon dioxide emissions (kg/hr) for intersection between Jalan Abdul Raof and diversion from SJKC Sin Hwa in 2011.	81
Figure 4.29	Existing maximum of carbon monoxide emissions (kg/hr) for intersection between Jalan Abdul Raof and diversion from SKJC Sin Hwa in 2011.	81
Figure 4.30	Existing maximum of hydrocarbon emissions (kg/hr) for intersection between Jalan Abdul Raof and diversion from SKJC Sin Hwa in 2011.	82
Figure 4.31	Existing maximum of oxides of nitrogen emissions (kg/hr) for intersection between Jalan Abdul Raof and diversion from SKJC Sin Hwa in 2011	82
Figure 4.32	Schematic Geometric layout of the existing condition signalized intersection between Jalan Taiping, Jalan Sekolah and Diversion from Bank Islam in 2011.	83
Figure 4.33	Schematic geometric layout of existing signal phasing at signalized intersection between Jalan Taiping , Jalan Sekolah and diversion from Bank Islam in 2011	84
Figure 4.34	Average fuel consumption and pollutant emissions at signalized intersection between Jalan Taiping, Jalan Sekolah and diversion from Bank Islam in 2011.	87
Figure 4.35	Average pollutant emissions at signalized intersection between Jalan Taiping, Jalan Sekolah and diversion from Bank Islam in 2011.	88

Figure 4.36	Existing maximum of fuel consumption (L/hr) for Intersection between Jalan Taiping, Jalan Sekolah and diversion from Bank Islam in 2011.	89
Figure 4.37	Existing maximum of carbon dioxide emissions (kg/hr) for intersection Jalan Taiping, Jalan Sekolah and diversion from Bank Islam in 2011.	89
Figure 4.38	Existing maximum of carbon monoxide emissions (kg/hr) for intersection Jalan Taiping , Jalan Sekolah and diversion from Bank Islam in 2011	89
Figure 4.39	Existing maximum of hydrocarbon emissions (kg/hr) for Intersection between Jalan Taiping , Jalan Sekolah and diversion from Bank Islam in 2011	90
Figure 4.40	Existing maximum of oxides of nitrogen emissions (kg/hr) for intersection between Jalan Taiping, Jalan Sekolah and diversion from Bank Islam in 2011.	90
Figure 4.41	Schematic geometric layout of The existing condition signalized intersection between Jalan Taiping and Jalan Perusahaan in 2011	91
Figure 4.42	Schematic geometric layout of existing signal phasing at signalized intersection between Jalan Taiping and Jalan Perusahaan in 2010 and 2011.	92
Figure 4.43	Schematic layout of the proposed improvement for signalized intersection between Jalan Taiping and Jalan Perusahaan in 2003 and 2007.	92

Figure 4.44	Schematic layout of the proposed improvement for signalized intersection between Jalan Taiping and Jalan Perusahaan in 2011	97
Figure 4.45	Proposed improvement signal phasing at signalized intersection between Jalan Taiping, and Jalan Perusahaan in 2010 and 2011	98
Figure 4.46	Average fuel consumption and pollutant emissions at signalized intersection between Jalan Taiping, and Jalan Perusahaan in 2011.	99
Figure 4.47	Average fuel consumption and pollutant emissions at signalized intersection between Jalan Taiping, and Jalan Perusahaan in 2011	99
Figure 4.48	Average pollutant emissions at signalized intersection between Jalan Taiping, and Jalan Perusahaan in 2011.	100
Figure 4.49	Average pollutant emissions at signalized intersection between Jalan Taiping, and Jalan Perusahaan in 2010.	100
Figure 4.50	Existing maximum of fuel consumption (L/hr) for intersection between Jalan Taiping and Jalan Perusahaan in 2011.	101
Figure 4.51	Existing maximum of carbon dioxide emissions (L/hr) for intersection between Jalan Taiping and Jalan Perusahaan in 2011.	102
Figure 4.52	Existing maximum of carbon monoxide emissions (kg/hr) for Intersection between Jalan Taiping and Jalan Perusahaan in 2011	102
Figure 4.53	Existing maximum of hydrocarbon emissions (kg/hr) for	103

	Intersection between Jalan Taiping and Jalan Perusahaan in 2011.	
Figure 4.54	Existing maximum of oxides of nitrogen emissions (kg/hr) for intersection between Jalan Taiping and Jalan Perusahaan in 2011	103
Figure 4.55	Schematic geometric layout of the existing condition at intersection between Jalan Taiping and Federal Route 1 In Year 2011.	104
Figure 4.56	Schematic geometric layout of the existing condition at intersection between Jalan Taiping and Federal Route 1 In 2011.	105
Figure 4.57	Schematic layout of the proposed improvement for signalized intersection between Jalan Taiping and Federal Route 1 in 2011	107
Figure 4.58	Proposed improvement signal phasing at signalized intersection between Jalan Taiping and Federal Route 1 in 2011	108
Figure 4.59	Average fuel consumption and pollutant emissions at signalized intersection between Jalan Taiping, and Federal Route 1 in 2011	112
Figure 4.60	Average fuel consumption and pollutant emissions at signalized intersection between Jalan Taiping, and Federal Route 1 in 2010	113
Figure 4.61	Average pollutant emissions at signalized intersection between Jalan Taiping, and Federal Route 1 in 2011	113

Figure 4.62	Average pollutant emissions at signalized intersection between Jalan Taiping, and Federal Route 1 in 2010	114
Figure 4.63	Existing maximum of fuel consumption (L/hr) for intersection between Jalan Taiping, and Federal Route 1 in 2011.	115
Figure 4.64	Existing maximum of carbon dioxide emissions (kg/hr) for Intersection between Jalan Taiping, and Federal Route 1 in 2011.	115
Figure 4.65	Existing maximum of carbon monoxide emissions (kg/hr) for intersection between Jalan Taiping, and Federal Route 1 in 2011.	115
Figure 4.66	Existing maximum of hydrocarbon emissions (kg/hr) for intersection between Jalan Taiping, and Federal Route 1 in 2011.	116
Figure 4.67	Existing maximum of oxides of nitrogen emissions (kg/hr) for intersection between Jalan Taiping, and Federal Route 1 in 2011.	116

LIST OF PLATES

		Page
Plate 2.1	Location of selected sites along Jalan Taiping and Jalan Abdul Raof in Parit Buntar, Perak Darul Ridzuan in 2010	35
Plate 2.2	Location of selected sites along Jalan Taiping and Jalan Abdul Raof in Parit Buntar, Perak Darul Ridzuan in 2011	35

LIST OF TABLES

	Page
Table 2.1 Emissions Standard of For a diesel engine having a total mass exceeding 3.5 tonnes	10
Table 2.2 Emissions Standard of For a diesel engine having a total mass not exceeding 3.5 tonnes	11
Table 2.3 The Malaysian Petrol Standards	11
Table 2.4 The Malaysian Diesel Standards	12
Table 2.5 Motor Vehicular Level of Service (LOS) criteria at intersection according to HCM 2000 Method.	23
Table 2.6 Description of Level of service	24
Table 2.7 Factor affecting the saturations flow	25
Table 2.8 Definition of intersection related terminology	26
Table 3.1 Example Sheet Of The Traffic Count	37
Table 3.2 Classification of vehicles	38
Table 3.3 Passengers car equivalent (Arahan Teknik (Jln) 13/87- A Guide on Geometric Designs of Road)	41
Table 3.4 Basic saturation flows in through car units per hour.	44
Table 4.1 Signal Timing For Existing Condition in 2010 and 2011 at Signalized Intersection Between Jalan Taiping, Jalan Padang And Jalan Lintang	54
Table 4.2 Peak Hour Traffic Volume in 2010 And 2011 at Signalized Intersection Between Jalan Taiping, Jalan Padang And Jalan Lintang	55